

SURVEY &  
REMONUMENTATION

MAY - 1 1995

COMMISSION

COPY

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED  
WASHTENAW COUNTY, MI

FEB 1 8 46 AM '95

PEGGY M. HAINES  
COUNTY CLERK/REGISTER

-COPY-

For corners in

WASHTENAW

( County )

Located In:

Corner Code #

1. Public Land Survey

T 4 S R 4 E

1-9

2. Property controlling  
in Section

S T R

3. Miscellaneous

S T R

Property in Sec.

S T R

4. Lot No. , Recorded Plot

5. Private Claims

LIBER 1 PAGE 338 RM  
COPY  
Register of Deeds Stamp & File Number

I, Paul V. Schwimmer, in a field survey on October 22, 19 93,  
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned  
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the  
current manual of survey instructions of the United States Department of the Interior, Bureau of Land  
Management or by decree of a Court of Law and/or that the corner points mentioned in lines 3,4 and 5  
above were in conformance with the rules of the Michigan Board of Land Surveyors or by Decree of a  
Court of Law; established, re-established, monumented, re-monumented, recovered, found as  
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded  
on this certificate

A. Description of original monument and accessories and/or subsequent restoration:

G.L.O. Wood Post

- 1) W. Oak 14" N 03° E 15 links
- 2) W. Oak 12" S 35° E 8 links

- Found 1/2" Iron Pipe  
on extension of fence line North
- 3) Hickory 20" N 75° W 121.10'
- 4) 2" Steel fence pole North 24.5'
- 5) North edge of gravel 8.0'
- 6) South edge of gravel 10.2'

Norman N. Fahrner LS# 17620  
Survey L1497 P237  
11/8/74

B. Description of corner evidence and/or method applied in restoring or reestablishing corner:

Found 1/2" Iron Pipe 4" below the road surface.

Removed iron pipe, checked for other iron pipes and found none.

- 4) Remains of 2" steel post in concrete, 3" below ground, North 24.45'
- 5) North edge of gravel 8.5'
- 6) South edge of gravel 9.2'

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:  
Replaced 1/2" iron pipe with 1" x 24" iron pipe with 2" aluminum Remonumentation cap 6" below the surface of the gravel road.

Set additional accessories

- 7) Telephone pole S 85° E 292.32' to a PK nail in N. side.
- 8) Light pole N 77° E 283.98' to PK nail in S. side.
- 9) Power pole N 43° W 226.07' to PK nail in SW side.
- 10) Power pole N 54° E 305.40' to PK nail in NW side.
- 11) NW corner of house N 63° E 298.70'

I believe this point should be accepted as the best available evidence of the original corner.

Signed by Paul V. Schwimmer

Date 12/29/94

Surveyor's Michigan License No. 24618

APPROVED

DATE 12/12/94

CO. REP. KJ

|    |    |    |    |    |    |    |    |    |    |   |   |   |   |
|----|----|----|----|----|----|----|----|----|----|---|---|---|---|
|    | A  | B  | C  | D  | E  | F  | G  | H  | I  | J | K | L | A |
| 2  | 6  | 5  | 4  | 3  | 2  | 1  |    |    |    |   |   |   |   |
| 3  |    |    |    |    |    |    |    |    |    |   |   |   |   |
| 4  | 7  | 8  | 9  | 10 | 11 | 12 |    |    |    |   |   |   |   |
| 5  |    |    |    |    |    |    |    |    |    |   |   |   |   |
| 6  | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 |   |   |   |   |
| 7  |    |    |    |    |    |    |    |    |    |   |   |   |   |
| 8  | 18 | 20 | 21 | 22 | 23 | 24 |    |    |    |   |   |   |   |
| 9  |    |    |    |    |    |    |    |    |    |   |   |   |   |
| 10 | 30 | 29 | 28 | 27 | 26 | 25 |    |    |    |   |   |   |   |
| 11 |    |    |    |    |    |    |    |    |    |   |   |   |   |
| 12 | 31 | 32 | 33 | 34 | 35 | 36 |    |    |    |   |   |   |   |
| 13 |    |    |    |    |    |    |    |    |    |   |   |   |   |

