APPROVED  DATE 9-23-96  CO. REF. 19  LAND CORNER RECORDATION OF Filing Requirement of Act 74, Mich For corners in  WASHTENAW  Located In: Corner Code #  1. Public Land Survey  T4S R6E H-13	h. PA. 1970 SECORES 15 MIN TY
T R T R T R T R T R T R T R T R T R T R	Liber ÜÜÜÜİ Page ÜESO berk
4. Lot No, Recorded Plat	2 6 5 3 2 3 4 7 8 9 10 11 1 96 15 14 96 18 17 16 15 14 96 18 17 16 15 14 96 18
A. Description of original monument and accessories and/or subsequent restored 1819 G.L.O. SET WOOD POST.  15" LOCUST S 41° W 5 LKS  12" OAK S 27° E 14 LKS	ation:
GRIDBOOK: NOTHING	REMONUMENTATION  MAY 0 5 1997
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:  SEARCHED FOR EVIDENCE OF CORNER AND FOUND NOTHING. THERE ARE NO OCCUPATION LINES NORTH OR SOUTH OF CORNER. SET STAKE MIDWAY AND ON LINE BETWEEN I—13 AND G—13 AND DUG FOR CORNER, FOUND NOTHING. REFERRED TO GLO FOR CLOSING DISTANCES AT THE NW AN NE CORNERS OF SECTION 3 MILAN TWP. AVÉRAGED THE CLOSING DISTANCES AND SEARCHED FOR N 1/4 CORNER OF SECTION 3 OF MILAN TWP. 60'+/— WEST OF H—13, FOUND NOTHING. FOUND CROP LINE TO SOUTH AT 70' WEST OF G—13, AND SEARCHED FOR CORNER, FOUND NOTHING. S A 1" IRON PIPE MIDWAY AND ON LINE BETWEEN I—13 AND G—13.	
C. Description of monument for corner and accessories established to perpetuate locating the AFTER A CAREFUL STUDY OF THE RECORD DOCUMENTATION UNDER MY DIRECT SUPERVISION, I FIND THIS CORNER AS AND FAITHFUL REESTABLISHMENT OF THE POSTION OF THE AND REMONUMENTATION CAP STAMPED 37277 MIDWAY AN SET PK/RT S/SIDE OF 24" ELM N 60° W 32.73'  SET PK/RT S/SIDE OF 18" CHERRY N 80° W 35.91'  SET PK/RT N/SIDE OF 10" HICKORY N 75° W 45.41'  SET PK/RT S/SIDE OF 28" HICKORY N 85° W 73.94'  SET PK/RT N/SIDE OF 2" BOX ELDER EAST 17.56'  Signed by Date  Surveyor's Michigan License No. 37277	ON AND FIELD OBSERVATIONS, MADE REMONUMENTED TO BE A CAREFUL E ORIGINAL CORNER. SET A 1" IRON PI ID ON LINE BETWEEN I-13 AND G-13.  OF MICHOPATRICK L  HASTINGS  PROFESSIONAL  GURVEYOR