

SURVEY &
REMONUMENTATION

MAY - 1 1995

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

COPY

RECORDED
WASHTENAW COUNTY, MI

FEB 1 9 00 AM '95

PEGGY H. NAINES
COUNTY CLERK/REGISTER

For corners in

Washtenaw
(County)

Located In:

Corner Code ##

- | | | | | | |
|-------------------------|---|----|---|----|------|
| 1. Public Land Survey | T | 4S | R | 7E | K-12 |
| | T | | R | | |
| | T | | R | | |
| | T | | R | | |
| 2. Property Controlling | S | | T | R | |
| in Section | S | | T | R | |
| 3. Miscellaneous | S | | T | R | |
| Property in Sec. | S | | T | R | |

LIBER

1 PAGE 391 RM

COPY

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

Thomas L. Sutherland in a field survey on November 15, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(W.C.R.C. 1935)
Found a piece of limestone standing on end below which was an old wood stake. Re-set with 1 1/2" x 36" Iron Pipe, Stones and Bricks 6" Y. Oak S70°W 26.8 2 Right-of-Way Pipes

(Kenneth Suydam #17636, 1972)
Nail and Washer in 40" Red Oak West/Southwest 25.30
Nail and Washer in 10" Hickory South/Southwest 101.00

(Atwell-Hicks, 1980)
1" Iron Pipe
32" R. Oak S70°W 26.1
12" S. Hickory S25°W 102.0
5" R. Oak N80°E 36.2
16" B. Willow N85°E 50.9
Right-of-Way Iron EAST 32.95

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 3/4" Iron Pipe 3" below gravel surface over larger iron surrounded by bricks and stones 18" below gravel surface. Adjusted 3/4" iron to 6" below gravel surface with aluminum Washtenaw County Remonumentation Cap.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

3/4" Iron Pipe with Aluminum Washtenaw County Remonumentation Cap
40" Oak S70°W 26.04 to Nail
W/W.C.R. Tag on SE Side
1/2" Iron R.O.W. Pipe EAST 33.15
15" Hickory S15°W 101.46 to Nail
W/W.C.R. Tag on E. Side
12" Pine S40°E 50.10 to Nail
W/W.C.R. Tag on SW Side
20" Oak N45°E 48.05 to Nail
W/W.C.R. Tag on NW Side

I conclude that after careful study of the record documentation and field observations, that this corner is a careful and faithful perpetuation of the position of the original corner

APPROVED

DATE 11/28/94

CO. REP. K

Signed by

Thomas L. Sutherland

Surveyor's Michigan License No. #24620

Date

December 14, 1994

